

MECHANICAL REPORT

REG: **NH56 EKD**

VEHICLE DESCRIPTION:

VOLKSWAGEN

GOLF

SILVER


ODOMETER:

68261 M

DATE OF INSPECTION:

21/10/2011

ENGINE BAY



✓ **Requires Charging**

Engine Oil Level	✓ OK
No Oil Contamination Visible	✓ OK
Brake Fluid Level	✓ OK
Power Steering Fluid Level	✓ OK
Coolant Level	✓ OK

ENGINE RUNNING

Starts	✓ OK
Engine Runs Smoothly	✓ OK
No Excessive Engine Smoking	✓ OK
Drive Belt Noise	✓ OK
Power Steering Pump Noise	✓ OK
Exhaust Condition (Not Blowing & Secure)	! Requires Attention
Static Gear Selection (Engine Running)	✓ OK

INTERIOR CHECKS

Engine Management Light	! Illuminated - Amber
ABS Warning Light	✓ Not Illuminated
Service Indicator Light	✓ Not Illuminated
Brake Wear Indicator Light	✓ Not Illuminated
Oil Warning Light	✓ Not Illuminated
Airbag Warning Light	✓ Not Illuminated

TYRE CONDITION

	Outer	Middle	Inner	
N/S/F	1 mm	1 mm	0 mm	! Requires Attention
N/S/R	4 mm	3 mm	4 mm	! Replace Soon
O/S/F	5 mm	4 mm	4 mm	! Replace Soon
O/S/R	7 mm	6 mm	6 mm	✓ OK

LCV (ADDITIONAL EQUIPMENT)

	Outer	Middle	Inner	
N/S/R				
O/S/R				

Tailift / Ancillary Equipment

DYNAMIC OPERATION

Brake Test 69 % ✓ OK	Hand Brake Test 45 % ✓ OK
1st and Reverse Drive Test	✓ OK
Clutch / Auto Drive Take Up	✓ OK
Suspension Noise / Ride Height	✓ OK
Aircon (Excl. Temp and Gassing Test)	✓ OK
Sat Nav Operates (Excl Functionality)	Not Applicable
ICE Operates (Excl Functionality)	✓ OK
Central Locking (Excl Electronic Key Fob)	✓ OK
Electric Hood / Sunroof	Not Applicable

Notes / Comments
 ENGINE MANAGEMENT LIGHT IS A FAULTY OIL PRESSURE VALVE